



Rugged, Versatile, Fast-Erecting Cranes of Unique Capability

WE ARE LOCATED AT:

Head Office & Training
Centre Freshwater Road,
Dagenham,
Essex
RM8 1RX

Max Lifting Capacity

450t
(radius 3m)

Lattice jib up to

84m

Telescopic boom
up to

85m

Number of axles


8

Total ballast

134t

Tight spots and rough terrain... no problem


Dimensions





VarioBallast®



VarioBase®




SingleEngine




- | | | | | |
|-----------------------|-----------------------|-------------------------------------|------------------------|-----------------|
| • Mobile Cranes | • Mini Crawler Cranes | • Hiabs | • Low-Loaders | • Driver CPC |
| • Mobile Tower cranes | • Spider cranes | • Machinery Removals & Installation | • General haulage | • FORS Training |
| • Crawler Cranes | • Contract Lifting | • Specialist Transport | • CPCS Training Centre | |

While every care has been taken in the preparation of the ratings given in this leaflet, and all reasonable steps have been taken to check the accuracy of the information, The Company cannot accept responsibility for any inaccuracy in respect of any matter arising out of, or in connection with the use of these tables.




S3012.01

While every care has been taken in the preparation of the ratings given in this leaflet, and all reasonable steps have been taken to check the accuracy of the information, The Company cannot accept responsibility for any inaccuracy in respect of any matter arising out of, or in connection with the use of these tables




While every care has been taken in the preparation of the ratings given in this leaflet, and all reasonable steps have been taken to check the accuracy of the information, The Company cannot accept responsibility for any inaccuracy in respect of any matter arising out of, or in connection with the use of these tables

Duty Charts



While every care has been taken in the preparation of the ratings given in this leaflet, and all reasonable steps have been taken to check the accuracy of the information, The Company cannot accept responsibility for any inaccuracy in respect of any matter arising out of, or in connection with the use of these tables.

Duty Charts



While every care has been taken in the preparation of the ratings given in this leaflet, and all reasonable steps have been taken to check the accuracy of the information, The Company cannot accept responsibility for any inaccuracy in respect of any matter arising out of, or in connection with the use of these tables